



PCN: PCN-CCX-42646-009-0

Product Change Notice

Issue Date: October 13, 2016

Change Type:

Change in Recommendation for new designs

Parts Affected:

BCM53124SKMMLG

BCM53124B0SKMMLG

Description and Extent of Change:

Please be advised that **BCM53124SKMMLG** and **BCM53124B0SKMMLG** are no longer recommended for new designs. All new designs should instead use **BCM53134SKFBG**

Reasons for Change:

Improved performance, power consumption, and longer lifetime in production for **BCM53134SKFBG**

Effect of Change on Fit, Form, Function, Quality, or Reliability:

BCM53134SKFBG is NOT pin-to-pin compatible with **BCM53124SKMMLG** and **BCM53124B0SKMMLG**. **BCM53134SKFBG** supports same functions, quality and reliability at significantly lower power consumption

Effective Date of Change:

Date of this Notice.

Qualification Data:

Qualification data has been generated and approved.

Please contact your Broadcom Limited field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.