A Littelfuse Company

PRODUCT DISCONTINUATION NOTICE

PDN No.: USA 2018-003

IXYS PRODUCT TYPE/PN	*TYPE: 1100V MOSFET*	*RECOMMEND REPLACEMENT:*
IXTH13N110		**IXFH16N120P**

REASON FOR DISCONTINUATION: ***OBSOLETE TECHNOLOGY , LACK OF DEMAND***

LAST TIME ORDER DATE: ***CONSULT WITH THE FACTORY***
LAST TIME DELIVERY DATE: ***CONSULT WITH THE FACTORY***

INTERNAL REFERENCE: ***N/A***

In case of any question, please contact: Sudhir Kommineni , IXYS General Manager , Milpitas CA S.Kommineni@ixys.net

INITIATOR	TITLE/FUNCTION	DATE	E-MAIL
GORDON ROSETE	DEPT HEAD QA, IXYS MILPITAS	FEBRUARY 28, 2018	G.ROSETE@IXYS.NET

CUSTOMER RESPONSE:

(PLEASE FILL IN AND RETURN BY E-MAIL, FAX OR MAIL WITHIN 4 WEEKS)

☐ for further questions/ information
please comment

Company: _____
Name & Position _____
Phone / Fax No: _____

COMMENTS:_____