



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M001017

DATE: 01-Dec-2020

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	78P2351-IGT/F	N/A	01-Dec-2020	30-May-2021	Part can no longer be manufactured
Discontinuance	78P2351R-IM/F	N/A	01-Dec-2020	30-May-2021	Part can no longer be manufactured
Discontinuance	MAX11960ETJ+	N/A	01-Dec-2021	30-May-2022	Part can no longer be manufactured
Discontinuance	MAX11960ETJ+T	N/A	01-Dec-2021	30-May-2022	Part can no longer be manufactured
Discontinuance	MAX6444US16K/V+T	N/A	01-Dec-2020	30-May-2021	Part can no longer be manufactured
Discontinuance	MAX9140AAXK/V+	MAX49140AXK/V+	01-Dec-2021	30-May-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 01-Jan-2021