

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

**Implementation of a CSA Mark Logo on an existing BPL Label and  
introduction of a datasheet update affecting dedicated products in package  
PG-TISON-8-1**

N° 044/16

## Implementation of a CSA Mark Logo on an existing BPL Label and introduction of a datasheet update affecting dedicated products in package PG-TISON-8-1

► Products affected:	Sales Name	SP N°	OPN	Package
	TLI4970-D025T4	SP001323154	TLI4970D025T4XUMA1	PG-TISON-8-1
	TLI4970-D025T5	SP001323150	TLI4970D025T5XUMA1	PG-TISON-8-1
	TLI4970-D050T4	SP000917088	TLI4970D050T4XUMA1	PG-TISON-8-1
	TLI4970-D050T5	SP001323146	TLI4970D050T5XUMA1	PG-TISON-8-1



### ► Detailed Change Information:

**Subject:** Implementation of a CSA Mark Logo on an existing BPL Label affecting dedicated products in package PG-TISON-8-1.

**Reason:**

- Certification by CSA requires visibility on label
- Datasheet is extended with additional information for customer

### Description:

<u>Old</u>	<u>New</u>						
<ul style="list-style-type: none"> <li>■ Barcode (BPL) Label without CSA Mark logo</li> </ul> 	<ul style="list-style-type: none"> <li>■ Barcode (BPL) Label with CSA Mark Logo</li> </ul> 						
<ul style="list-style-type: none"> <li>■ Datasheet Rev. 1.0</li> </ul>	<ul style="list-style-type: none"> <li>■ Datasheet Rev. 1.1</li> </ul> <p>Changes Rev. 1.0 vs 1.1 done:</p> <table border="1"> <tr> <td>Page 21</td> <td>Chapter 3.6 added</td> </tr> <tr> <td>Page 12</td> <td>Added note on default bandwidth.</td> </tr> <tr> <td>Page 18</td> <td>Table 3.4 "OCD Output Parameter" on Page 18 updated. Added row for De-glitch filter time. Added note on default OCD level.</td> </tr> </table>	Page 21	Chapter 3.6 added	Page 12	Added note on default bandwidth.	Page 18	Table 3.4 "OCD Output Parameter" on Page 18 updated. Added row for De-glitch filter time. Added note on default OCD level.
Page 21	Chapter 3.6 added						
Page 12	Added note on default bandwidth.						
Page 18	Table 3.4 "OCD Output Parameter" on Page 18 updated. Added row for De-glitch filter time. Added note on default OCD level.						

► **Product Identification:** Product can be identified due to change in visual appearance of the barcode label.

N° 044/16

► **Impact of Change:**

No change in form, fit or function of the product.

► **Attachments:**

Datasheet: 4\_cip16044

► **Intended start of delivery:**

October 2016.

If you have any questions, please do not hesitate to contact your local Sales office.