



Product Change Notification / SYST-03YDHP471

Date:

04-Feb-2021

Product Category:

Bluetooth Module

PCN Type:

Document Change

Notification Subject:

Data Sheet - RN4870/71 Bluetooth Low Energy Module Data Sheet

Affected CPNs:

[SYST-03YDHP471_Affected_CPN_02042021.pdf](#)

[SYST-03YDHP471_Affected_CPN_02042021.csv](#)

Notification Text:

SYST-03YDHP471

Microchip has released a new Product Documents for the RN4870/71 Bluetooth Low Energy Module Data Sheet of devices. If you are using one of these devices please read the document located at [RN4870/71 Bluetooth Low Energy Module Data Sheet](#).

Notification Status: Final

Description of Change:

- 1) Added new description for VDD_IO pins in Table 1-2.
- 2) Added labeling information of Brazil for RN4871 module.
- 3) Added Section 11.1.3 "Approved Antennas", Section 11.2.3 "Approved Antennas" and Section 11.8 "Brazil".
- 4) Updated Section 11.2.1 "Labeling and User Information Requirements", Section 11.3 "Europe" and Section 11.7 "China".

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 04 Feb 2021

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[RN4870/71 Bluetooth Low Energy Module Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

RN4870-I/RM128
RN4870-I/RM130
RN4870-I/RM140
RN4870-V/RM118
RN4870-V/RM140
RN4870U-V/RM118
RN4871-I/RM128
RN4871-I/RM130
RN4871-I/RM140
RN4871-V/RM118
RN4871-V/RM130
RN4871-V/RM140
RN4871U-V/RM118