

PRODUCT DISCONTINUANCE NOTIFICATION

May 18, 2022

Dear Valuable Customer,

Thank you for your use and support of MPS' product family. Please be advised MPS will discontinue the production of the following part(s):

MP86963DUT-LF-Z MP86981DU-LF-Z MPQ8632DGLE-6-Z MPQ8632DGLE-12-Z MPQ88642GLE-Z

The replacement part(s) will be

MP86963DUT-LF-Z: MP86901-CGLT–Z MP86981DU-LF-Z: MP86901-CGLT–Z MPQ8632DGLE-6-Z: MPQ8632GLE-6-Z MPQ8632DGLE-12-Z: MPQ8632GLE-12-Z MPQ88642GLE-Z: MPQ8632GLE-10

Which can be available immediately.

MPS will offer a special last time buy to deplete our current inventory and allow you to purchase material for your design. Final purchase orders for (MP86963DUT-LF-Z, MP86981DU-LF-Z, MPQ8632DGLE-6-Z, MPQ8632DGLE-12-Z, MPQ88642GLE-Z) must be received no later than (10/20/2022). When this inventory is depleted, no new inventory will be available. All orders must be delivered by (4/20/2023). These orders cannot be cancelled or changed. The minimum order quantity must be (5k) units. For orders placed after (10/20/2022), MPS reserves the right to reject the request.

Our sales personnel and application engineers can assist you with evaluating the best MPS solutions to meet your application needs.

Thank you for your continuous business.