



## Product/Process Change Notice - PCN 14\_0066 Rev. B

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. **Any inquiries or requests with this PCN (additional data or samples) must be sent to ADI within 30 days of publication date.** ADI contact information is listed below.

*Note: Revised fields are indicated by a red field name. See Appendix B for revision history.*

**PCN Title:** ADG5233 and ADG5234 TSSOP Redesign resulting in Data Sheet Specification Changes

**Publication Date:** 23-Jul-2015

**Effectivity Date:** 23-Jul-2015 *(the earliest date that a customer could expect to receive changed material)*

### Revision Description:

Change over datecode for TSSOP material corrected.

### Description Of Change

All layer redesign of the ADG5233 and ADG5234 die which results in improved ESD ratings and affects product specifications for charge injection, pin capacitance, timing, bandwidth, cross talk and isolation. Please see attachment for change details.

### Reason For Change

Improvement for ESD rating, charge injection, and timing specifications.

### Impact of the change (positive or negative) on fit, form, function & reliability

This redesign will not affect the form, fit, function, quality or reliability of the ADG5233 and the ADG5234

### Product Identification *(this section will describe how to identify the changed material)*

The date code changeover is 1522

### Summary of Supporting Information

Qualification has been performed per ADI0012, Procedure for Qualification of New or Revised Processes. See attached Qualification Report Summary.

### Supporting Documents

**Attachment 1: Type:** Datasheet Specification Comparison

ADI\_PCN\_14\_0066\_Rev\_B\_ADG5233\_34 RevB to RevC Data Sheet changes.pdf

**Attachment 2: Type:** Qualification Results Summary

ADI\_PCN\_14\_0066\_Rev\_B\_Qual Summary ADG5233 ADG5234.pdf

**For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives.**

**Americas:** PCN\_Americas@analog.com

**Europe:** PCN\_Europe@analog.com

**Japan:** PCN\_Japan@analog.com

**Rest of Asia:** PCN\_ROA@analog.com

**Appendix A - Affected ADI Models**

**Existing Parts - Product Family / Model Number (4)**

ADG5233 / ADG5233BRUZ	ADG5233 / ADG5233BRUZ-RL7	ADG5234 / ADG5234BRUZ	ADG5234 / ADG5234BRUZ-RL7	
-----------------------	---------------------------	-----------------------	---------------------------	--

**Appendix B - Revision History**

<b>Rev</b>	<b>Publish Date</b>	<b>Effectivity Date</b>	<b>Rev Description</b>
Rev. -	11-Sep-2014	10-Dec-2014	Initial Release
Rev. A	09-Dec-2014	10-Dec-2014	Adding date code change over
Rev. B	23-Jul-2015	23-Jul-2015	Change over datecode for TSSOP material corrected.

Analog Devices, Inc.

DocId:3372 Parent DocId:None Layout Rev:7