



Micron Technology, Inc.
 8000 S. Federal Way
 PO Box 6
 Boise, ID United States

Mold Compound Change for Parallel NOR BGA at Micron, Muar for Automotive and non-Automotive

PCN: 31594

Published: 2015-09-25

Type:	Material Change - Product
Description:	Sumitomo mold compound supplier is converting to an environmentally green mold compound that does not contain Br or Sb based flame retardant systems. The green mold compound is already qualified and in production on other Micron products at Muar.
Reason:	Supply Flexibility/Security
Product Affected:	Parallel NOR BGA

Affected Micron Part Number Component	Recommended Replacement	Customer Part Number
M58LR128KB70ZB5E		
M58LR128KB70ZB5F		
M58LR128KB85ZB5E		M58LR128KB85ZB5E-ND
M58LR128KB85ZB5F		
M58LR128KB85ZB6E		
M58LR128KB85ZB6F		
M58LR128KT85ZB5E		M58LR128KT85ZB5E-ND
M58LR128KT85ZB5F		
M58LR128KT85ZB6E		
M58LR128KT85ZB6F		
M58WR064KB70ZB6E		
M58WR064KB70ZB6F		
M58WR064KB7AZB6E		
M58WR064KB7AZB6F		
M58WR064KT70ZB6E		
M58WR064KT70ZB6F		
M58WR064KT7AZB6E		
M58WR064KT7AZB6F		

*Materials that have been ordered are in **bold**.

Method of Identification: Date code on part marking

Micron Sites Affected: MMY – Muar_Malaysia

Sample Available: 2015-10-23

Qual Data Available: 2015-10-23

Product Ship Date: 2016-01-23

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Thank you

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.