

<b>Title of Change:</b>	Update to PD23762 series - 4Q2020 Product Discontinuance Notice with extended EOL Dates
<b>Last Time Buy Date:</b>	30 Jun 2024
<b>Last Ship Date:</b>	31 May 2025
<b>Contact information:</b>	Contact your local onsemi Sales Office or <a href="mailto:Madoka.Wynveen@onsemi.com">Madoka.Wynveen@onsemi.com</a>
<b>Type of notification:</b>	Customers must notify onsemi (< <a href="mailto:PCN.Support@onsemi.com">PCN.Support@onsemi.com</a> >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.

## Description and Purpose:

onsemi wishes to promptly inform our customer of our intent to extend current EOL dates due to very constrained capacity available for the T6 technology replacement.

onsemi has provided a list of replacement devices, where available, to aid in this process.

For those devices that have no recommended replacement identified, onsemi has partnered with Rochester Electronics and Flip Electronics who will carry any remaining device inventory to potentially allow for a continued source after onsemi has completed its business process.

PLEASE NOTE: onsemi may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

### Americas:

Tom Siegel (tom.siegel@onsemi.com)

☎ +1 765 868 5022

USA

### Japan:

Isao Usuki (isao.usuki@onsemi.com)

☎ +81 3 6880 1771

Japan

### Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)

☎ +421 33790 2229

Slovakia

### Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)

☎ +852 2689 0209

China

## List of Affected Parts:

**Note:** Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

Device to be Discontinued	Replacement part	Supplier
FDBL9401-F085	FDBL9401-F085T6	onsemi
FDBL9403-F085	FDBL9403-F085T6	onsemi
FDBL9406-F085HM	FDBL9406-F085T6	onsemi
FDBL9406-F085	FDBL9406-F085T6	onsemi

---

**Appendix A: Changed Products**

**PCN#: PD23762Z4**  
**Issue Date: Jun 27, 2022**

---

---

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
FDBL9406-F085			FDBL9406-F085T6	
FDBL9401-F085			FDBL9401-F085T6	