

PCN Number:	20150127002	PCN Date:	02/02/2015
Title:	Datasheet update for BQ24392/BQ24392-Q1		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

PCN Details

Description of Change:

The product datasheet(s) is being updated as summarize below.

Feature Bullet Change:

From: USB Battery Charging Specification Version 1.2 (BCv1.2) Compliant
 To: Detects Battery Charging Specification Version 1.2(BCv1.2) Compliant Chargers



bq24392

SLIS146C –JUNE 2012–REVISED JANUARY 2015

www.ti.com

Changes from Revision B (October 2014) to Revision C

Page

- Updated Features 1



BQ24392-Q1

SLIS160B –AUGUST 2014–REVISED JANUARY 2015

www.ti.com

Changes from Revision A (September 2014) to Revision B

Page

- Updated Features 1

The datasheet number will be changing.

Device Family	Change From:	Change To:
BQ24392	SLIS146B	SLIS146C
BQ24392-Q1	SLIS160A	SLIS160B

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/bq24392>

<http://www.ti.com/product/bq24392-q1>

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

Electrical specification performance changes as indicated above.

Changes to product identification resulting from this PCN:

None.

Product Affected:

BQ24392QRSER	BQ24392QRSERQ1	BQ24392RSER
--------------	----------------	-------------

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com