

To : Dear Valued Customers

## Product Discontinuance Notice

Subject : Products discontinue.															
Parts Affected :															
<table border="1"><thead><tr><th>Part No.</th><th>Package</th></tr></thead><tbody><tr><td>ASMCJ250(C)A-HF</td><td>SMC/DO-214AB</td></tr><tr><td>CDSURT4148-HF</td><td>0603/SOD-523F</td></tr><tr><td>CPDURT5V0C-HF</td><td>0603/SOD-523F</td></tr><tr><td>CDBURT0230L-HF</td><td>0603/SOD-523F</td></tr><tr><td>CDBURT0230LL-HF</td><td>0603/SOD-523F</td></tr><tr><td>CDBURT0230R-HF</td><td>0603/SOD-523F</td></tr></tbody></table>		Part No.	Package	ASMCJ250(C)A-HF	SMC/DO-214AB	CDSURT4148-HF	0603/SOD-523F	CPDURT5V0C-HF	0603/SOD-523F	CDBURT0230L-HF	0603/SOD-523F	CDBURT0230LL-HF	0603/SOD-523F	CDBURT0230R-HF	0603/SOD-523F
Part No.	Package														
ASMCJ250(C)A-HF	SMC/DO-214AB														
CDSURT4148-HF	0603/SOD-523F														
CPDURT5V0C-HF	0603/SOD-523F														
CDBURT0230L-HF	0603/SOD-523F														
CDBURT0230LL-HF	0603/SOD-523F														
CDBURT0230R-HF	0603/SOD-523F														
Reason for Discontinuance :															
Due to low demand, the part listed below will be discontinued.															
Alternative Products :															
Please contact sales person or manufacturer's representative.															
Effective Date : Mar 31, 2022															
R&D Dept. Signature :	QA Dept. Signature :														
															